

# Clifton Pedestrian Circulation Study

## Final Report

Prepared for:

Mesa County Regional Transportation Planning Office  
750 Main Street, 1<sup>st</sup> Floor  
Grand Junction, CO 815021  
(970) 255-7188

Prepared by:

LSC Transportation Consultants, Inc.  
516 North Tejon Street  
Colorado Springs, CO 80903  
(719) 633-2868

LSC #056690

October 30, 2006

# TABLE OF CONTENTS

Chapter	Title	Page
I	INTRODUCTION . . . . .	I-1
	Purpose of the Study . . . . .	I-1
	Study Area . . . . .	I-2
	Report Contents . . . . .	I-2
	Study Approach . . . . .	I-5
	Project Team . . . . .	I-5
	Current Issues and Priorities . . . . .	I-6
	Issues . . . . .	I-6
	Study Priorities . . . . .	I-6
	Interview with Local Resident . . . . .	I-7
II	REVIEW OF EXISTING PLANS AND DOCUMENTATION . . . . .	II-1
	Existing Plans . . . . .	II-1
	Clifton Transportation Study . . . . .	II-1
	2.1 Pedestrian and Bicycle Facilities . . . . .	II-1
	2.2 Transit System . . . . .	II-2
	Public Comments . . . . .	II-2
	Pear Park Neighborhood Plan . . . . .	II-3
	Urban Trails . . . . .	II-3
	Mesa County Public Works (2005-2010 Capital Investment Program) . . . . .	II-4
	Clifton/Fruitvale Community Plan . . . . .	II-4
	Initial Safety Review . . . . .	II-4
	US Access Board Review . . . . .	II-5
	Statewide Guide . . . . .	II-5
III	PUBLIC INPUT . . . . .	III-1
	Questionnaire Results . . . . .	III-1
	Residence . . . . .	III-2
	Use of Facilities . . . . .	III-2
	Facility Ratings . . . . .	III-5
IV	INITIAL FIELD INVESTIGATION . . . . .	IV-1
	Initial Analysis of Facility Location . . . . .	IV-1
	Development of Initial Inventory . . . . .	IV-1
	Facility Locations Using Aerial Photography . . . . .	IV-2
	Windshield Field Survey . . . . .	IV-2
V	PEDESTRIAN AND BICYCLE INVENTORY . . . . .	V-1
	Pedestrian and Bicycle Way Inventory . . . . .	V-1
	Map Features . . . . .	V-1
	Pedestrian Features . . . . .	V-2
	Bicycle and Mixed-Use Path Features . . . . .	V-2
	New Inventory . . . . .	V-2
	Pedestrian Features . . . . .	V-2
	Transit Stops . . . . .	V-3

VI	FACILITY DESIGN CONSIDERATIONS	VI-1
	Local Development	VI-1
	Land Use	VI-1
	Visioning	VI-2
	Sidewalks	VI-3
	On-Road Bike Facility Design Criteria	VI-7
	Design Considerations	VI-7
	Types of Facilities	VI-9
	Bike Lanes	VI-9
	Bus/Bike Lanes (Shared Lanes)	VI-11
	Shared Roadways	VI-12
	Wide Curb or Wide Outside Lane	VI-13
	Shoulder Bike-/Pedways	VI-13
	Traffic-Calmed Roadways	VI-15
	Off-Road Facility Design Criteria	VI-15
	Bikes on Sidewalks	VI-17
	Conflicts	VI-19
	Safety Issues	VI-26
	Improving Pedestrian/Bicyclist Safety	VI-27
	Speed Reduction	VI-28
	Signs	VI-28
	Crosswalks	VI-29
	Crossing Distances	VI-30
VII	TRANSIT PLANNING CONSIDERATIONS	VII-1
	Pedestrian Access-Ways	VII-1
	Sidewalks and Curbs	VII-3
	Cross Slopes	VII-3
	Walled Residential Areas	VII-5
	Rural Areas	VII-7
	Bus Stop Placement	VII-7
	Industry Standards	VII-7
	Roadway Configurations	VII-9
	Placement of Amenities	VII-9
	Bus Stop Spacing	VII-9
	Spacing Standards	VII-11
VIII	INITIAL EVALUATION AND IMPROVEMENTS	VIII-1
	Initial Evaluation	VIII-1
	Overall Rating	VIII-1
	Specific Problem Areas	VIII-1
	Curb Cuts	VIII-2
	Access to Transit Stops	VIII-3
	Crosswalk Accessibility	VIII-3
	Curb-and-Gutter	VIII-4
	Pedway Width	VIII-4
	Connectivity	VIII-5
	Safety	VIII-5
	Specific Commendable Characteristics	VIII-6

IX	CRITERIA METHODOLOGY . . . . .	IX-1
	Pedestrian Way Criteria . . . . .	IX-1
	Connection to School . . . . .	IX-2
	Network Connectivity . . . . .	IX-3
	Connection to Parks and Recreation Facilities . . . . .	IX-3
	Connection to Existing Bus Stop . . . . .	IX-3
	Connection to Existing Commercial Areas . . . . .	IX-4
	Within a City/County Right-of-Way (ROW) . . . . .	IX-4
	Received Public Comment . . . . .	IX-4
	A Planned Improvement . . . . .	IX-4
	Clifton Transportation Plan Recommended Project . . . . .	IX-5
	Bike and Trail Planning . . . . .	IX-5
	Preliminary Cost Estimating for Improvements . . . . .	IX-5
	Preliminary Project Priority . . . . .	IX-7
X	IMPROVEMENT RANKINGS . . . . .	X-1
	General Improvement Recommendations . . . . .	X-2
	Rankings of Prioritized Pedestrian Improvements . . . . .	X-5
	Rankings of Prioritized Bicycle/Trail Improvements . . . . .	X-11
XI	FUNDING MECHANISMS . . . . .	XI-1
	The Funding Process . . . . .	XI-2
	Possible Funding Mechanisms . . . . .	XI-3
	Government Sources . . . . .	XI-3
	Federal: Transportation . . . . .	XI-3
	Surface Transportation Program (STP) . . . . .	XI-4
	Safe Routes to School (SR2S) . . . . .	XI-4
	Transportation Enhancements . . . . .	XI-5
	Federal: Non-Transportation . . . . .	XI-6
	State: Transportation . . . . .	XI-6
	State: Non-Transportation . . . . .	XI-9
	Local Sources . . . . .	XI-10
	Determining Program Source . . . . .	XI-11

APPENDIX A: Current Newsletters

APPENDIX B: Accessibility Guidelines Summary

APPENDIX C: Survey Questionnaire

APPENDIX D: Survey Comments

APPENDIX E: Survey Results Graphs

APPENDIX F: Mesa County Subdivision Design Standards

APPENDIX G: Transportation Enhancement Projects

APPENDIX H: Common Terminology

## LIST OF TABULATIONS

Table	Title	Page
III-1	Walkability/Bikeability of Clifton . . . . .	III-5
VII-1	Typical Bus Stop Spacing . . . . .	VII-11
IX-1	Criteria and Associated Ratings and Weights . . . . .	IX-2
IX-2	Candidate Pedestrian Treatments . . . . .	IX-6
IX-3	Estimated Unit Costs . . . . .	IX-7
X-1	New Sidewalk Improvements . . . . .	X-9
X-2	Bike and Trail Improvements . . . . .	X-15
XI-1	Potential Sources of Funding . . . . .	XI-13

## LIST OF ILLUSTRATIONS

Figure	Title	Page
I-1	Clifton Study Area . . . . .	I-3
III-1	Do You Walk or Bike? . . . . .	III-2
III-2	Reason For Use . . . . .	III-3
III-3	Facility Use . . . . .	III-4
IV-1	Example Data Collection Area . . . . .	IV-4
V-1	Existing Conditions - North of I-70 Business Loop . . . . .	V-5
V-2	Existing Conditions - South of I-70 Business Loop . . . . .	V-7
V-3	Additional Inventory - North of I-70 Business Loop . . . . .	V-9
V-4	Additional Inventory - South of I-70 Business Loop . . . . .	V-11
VI-1	Attached Sidewalk . . . . .	VI-3
VI-2	Detached Sidewalk . . . . .	VI-3
VI-3	Brick Sidewalk . . . . .	VI-4
VI-4	Typical Roadway Cross Sections in the Grand Junction Area . . . . .	VI-5
VI-5	Two-Way Path Separated From Traveled Way . . . . .	VI-7
VI-6	On-Road Bike Lane . . . . .	VI-9
VI-7	Rumble Strip on Paved Shoulder . . . . .	VI-14
VI-8	Traffic-Calmed Roadway . . . . .	VI-15
VI-9	Bike Route on Sidewalk . . . . .	VI-17
VI-10	Typical Bicycle Path . . . . .	VI-25
VI-11	Textured Pavement . . . . .	VI-28
VI-12	Yield Sign . . . . .	VI-29
VI-13	Raised Crosswalk . . . . .	VI-29
VI-14	Curb Extensions . . . . .	VI-30

VII-1	Existing Clifton Bus Routes . . . . .	VII-2
VII-2	Excessive Cross Slope . . . . .	VII-4
VII-3	Walled Residential Access and Rural Access . . . . .	VII-6
VII-4	ADA Minimum Bus Stop Requirements . . . . .	VII-8
VII-5	Bus Turnout Specifications and Location Requirements . . . . .	VII-10
VII-6	Recommended Bus Stop Spacing . . . . .	VII-12
VIII-1	Existing Curb Cuts . . . . .	VIII-2
VIII-2	Street Overlay and Gutter Pan . . . . .	VIII-2
VIII-3	Shoulder Access to Transit Stop . . . . .	VIII-3
VIII-4	Non-Accessible Crossing . . . . .	VIII-3
VIII-5	Major Arterial Pedestrian Crossing . . . . .	VIII-3
VIII-6	Mountable Curb . . . . .	VIII-4
VIII-7	Gutter Pan with Attached Narrow Sidewalk . . . . .	VIII-4
VIII-8	Typical Sidewalk 3.5 Feet . . . . .	VIII-4
VIII-9	Sidewalks Not Connecting . . . . .	VIII-5
VIII-10	Sidewalks That “Go Nowhere” . . . . .	VIII-5
VIII-11	“Quick Fixes” . . . . .	VIII-5
VIII-12	Unsafe Transit Access . . . . .	VIII-6
X-1	Sidewalks with Probable Maintenance Issues . . . . .	X-4
X-2	Pedestrian Improvement Recommendations . . . . .	X-7
X-3	Bicycle and Trail Improvement Recommendations . . . . .	X-13